## CASE STUDY - BIRD NETTING BRIDGE

New York Overpass Underside of Bridge


## PEST BIRD SPECIES: PIGEONS


- ✓ Several hundred pigeons nesting under bridge.
  - o Years of bird droppings and nesting
- √ Heavy nesting materials on concrete columns and metal I-beams.
- ✓ Small population of non-target birds (Sparrows)
- √ Ample food/water supply in area

## BIRD CONTROL METHOD: BIRD EXCLUSION NETTING

- ✓ Black ¾" Bird Exclusion Netting was installed to exclude target pest bird (Pigeons) as well as (Sparrows)
- √ System completely removable.
- √ ZERO penetrations into the structure
- ✓ Clamp/Rod system allows access panel to be opened for complete access behind the netting for bridge inspections.
- ✓ Minimal visual impact

## PROJECT PHOTOS





- √ Complete steel frame construction
- ✓ Zero penetrations into the bridge structure
- √ Complete access behind the netting
- ✓ Complete bird EXCLUSION for all pest birds
- ✓ Contact Aviaway for all your Bird Control Projects.

